

Accident / Incident Report Closed



Unit/Department South Operation-Elyria	Process Area General Catalyst – Building 16	Site ELYRIA	Report Number 0084-SOPS-16-0038	
Report Date 03/02/2016	Incident Date 03/02/2016	Incident Time 02:00 AM	Copied From	
Incident Location Trimer area building 5C		Team Leader / Supervisor Douglas Stock	Reported By Robert Gavalek	
Title of Event (Limit to 90 characters) Solution leak from Stage #1 tower (seam) shortly after starting up unit.		Category <input type="checkbox"/> Safety & Health <input type="checkbox"/> Environmental	Division / Bus. Group / Subgroup Code CC / G-CCP	
Incident Classification				
<input type="checkbox"/> Near Miss	<input type="checkbox"/> Property Loss	<input type="checkbox"/> Contractor		
<input type="checkbox"/> Process Safety	<input type="checkbox"/> Citation / NOV	<input type="checkbox"/> Contractor Injury / Illness		
<input type="checkbox"/> Injury / Illness	<input type="checkbox"/> Health Exposure	<input type="checkbox"/> Contract Injury / Illness		
<input checked="" type="checkbox"/> Spill / Release	<input type="checkbox"/> Inspection	<input type="checkbox"/> PSM		
<input type="checkbox"/> Permit / Regulatory Deviation	<input type="checkbox"/> Major Incident	<input type="checkbox"/> Plant Upset		
<input type="checkbox"/> Fire	<input type="checkbox"/> Non-Occupational	<input type="checkbox"/> EHS Management System Failure		
<input type="checkbox"/> Odor Complaint	<input type="checkbox"/> RMP	<input type="checkbox"/> Other		
Describe Event / What Happened				
<p>The Trimer had been down to clean the stage 2 and 3 nozzles. At about 2am on 3/2/16 the Trimer was started back up. The blower and recirculation pumps were running but the Chem tank was not in use yet. The stage 1, 2, and 3 tanks had just been refilled after the maintenance work so the solution was mainly water and caustic (sodium hydroxide) at a pH of about 11. After running for about 2 minutes the operators that started the unit heard a loud pop. They observed water leaking from the stage 1 tower and immediately shut the Trimer off. Approximately 5 gallons of solution had leaked from the seam on stage 1 tower (a few feet below the recirculation inlet, even with the 2nd level mezzanine). The solution dripped down around tank #1 and did not cause any damage to equipment or injury.</p>				
Immediate Corrective Action or Response				
<p>The Trimer was shut off immediately after hearing the popping sound and seeing the water leaking from the stage #1 tower.</p>				
Immediate Cause				
<p>We were unable to determine what caused the rupture at the seam which led to the leaking solution.</p>				
Spill Release Type(s) Non RQ Spill / Release				
Chemical(s) Involved High pH process water with caustic and sulfides	CAS # N/A	Phy. State Liquid	Air 0	Land 0
			Water 0	Contmt 41
				Units lbs
Disposition of Material Material captured in sump and treated				
Weather Conditions	Skies:	Temperature:	Wind Direction:	Wind Speed:
Cause Narrative				
<p>It appears that the scrubber tower recirculation flows and the blower for the Trimer scrubber were started and ran for about 12 minutes. During this time the manual valves to the both RC 1 and RC 4 were closed which dead headed the scrubber (except for any tramp air that may be pulled in through the drops at the scrubber tanks). Most likely the scrubber towers have shown some embrittlement over time due to chemical attack and cycling of temperatures. The dead heading of the scrubber appears to have cracked the tower to the point where water overcame the suction and caused solution to leak through the cracked liner.</p>				
Contributing Causes		Root/Primary Causes		
<p>The current startup procedures do not have the requirement to have air vented to the scrubber</p>		<p>111 - Procedures 130 - 136 - Incomplete/Situation Not</p>		

at startup		Wrong/Incomplete	Covered
Current no inspection program of the inside of the scrubber towers	28 - Equipment Reliability Program Implementation LTA	36 - Predictive Maintenance LTA	38 - Monitoring LTA
A blank was previously installed on the vent air duct This allowed the trimmer scrubber to operate under excessive vacuum, resulting in damage to tower 1.	55 - Administrative/Management Systems	72 - Safety/Hazard/Risk Review	74 - Review LTA or Not Performed
Any known or potential off-site impacts?	No	PSM Incident?	No
Investigation Team	Estimated Cost: 1,200.00 USD		
	Douglas Stock; Terrence M Vanderbosch; Phillip Wright; Jefferson Lewis; Leon Zavodnik		

Item	Corrective Action(s) to prevent recurrence	Responsible Person	Target Date	Final Closed Date	VC Req	VE Req
1	Modify calciner walk down sheets to add venting of calciners to the scrubber during startup of the scrubber	Jefferson Lewis/NA/BASF	05/29/2016	05/27/2016	N	N
2	Remove the blank on vent air duct. Restore vent air system to service.	Terrence M Vanderbosch/BASF-CATALYSTS/BA SF	05/30/2016	05/27/2016	N	N
3	Develop a training 1-pager to review at the next safety meeting.	Jefferson Lewis/NA/BASF	04/15/2016	04/05/2016	N	N
4	Contact a 3rd party to design an appropriate vacuum-break system to eliminate manual operation of a slide gate on the 1st floor mezzanine.	Lee McClish/NA/BASF	08/31/2016	08/26/2016	N	N

Approved By:	
Manager / Dept. Head	Leon Zavodnik 04/03/2016 09:38 AM
EHS Unit Coordinator	Tim Anglin 03/30/2016 03:35 PM
Safety & I.H.	Nancy Gallagher 04/04/2016 12:01 PM
Team Leader / Supervisor	Valerie Douglas 04/04/2016 04:19 PM
Confidential	